

## Under Review Notification

Raised By: Scott Cameron

Product #: RBW6205G25031-3G

Date: Oct 6 2017

Product Name: CLAMP ASSY

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	PP Under Review	Product Specifications Under Review ("Bluefiles")		
RBW6205G25031-3G-1	RBW6205G25031-3G Rev 1	Y	N	N	Y	N	Y	N	17-701	Stop production
RBW6205G25031-3G	RBW6205G25031-3G Rev 1	Y	N	N	Y	N	Y	N	17-701	Stop production

**Description of Issue:**  
 Rev 1 drawing calls up ENERPAC A-205, and modifies it.  
 Design of part does not match ENERPAC A-205  
 Some discrepancies between OEM part photos and dimensions on drawing.  
 Drawing mentions adhesive to attach -3 to -1 but does not specify.

**Distribution:**

VP Operations Director of Operations Director Quality Assurance Director of Engineering	Chief Engineer Engineering Project Managers Engineering Clerk Customer Support Manager	Production Engineers Production Planners Purchasing Manager Technical Support	Product Manager - Solutions Provider
--	---	--	--------------------------------------